



LOCAL NOTICE TO MARINERS No. 10 of 2015

Final Update to Wreck at Entrance to Littlehampton Harbour

MARINERS ARE ADVISED that the previously reported wreck at the entrance to Littlehampton Harbour (marked by buoys and in position 50° 47.81'N, 000° 32.82'W) has been broken up and dispersed by recent storms.

The remainder of the wreckage has now been cut down to beach level.

All associated marker buoys in the area have now been removed.

Owners, Agents, Charterers, Marinas, Yacht Clubs and Recreational Sailing Organisations should ensure that the contents of this Notice are made known to the masters or persons in charge of their vessels or craft.

Billy Johnson
Harbour Master

27th November 2015