



LOCAL NOTICE TO MARINERS No. 04 of 2017

Goring Outfall South Cardinal Buoy Missing

MARINERS ARE ADVISED that the Goring South Cardinal buoy, marking the 1.5m DRYING obstruction around the low water line off Sea Lane in Goring, in position 50° 47.85'N, 000° 25.10'W (character Q(6)+LFl.15s) is missing.

Owners, Agents, Charterers, Marinas, Yacht Clubs and Recreational Sailing Organisations should ensure that the contents of this Notice are made known to the masters or persons in charge of their vessels or craft.

A handwritten signature in blue ink that reads "B Johnson".

Billy Johnson
Harbour Master

5th April 2017